

Update list of WinProladder V3.24

- **New “FUN” instruction**

None

- **New functions**

1.Add F199.TXTDF:LADCOPY:CLOSE’s application ◦

- **Function revision**

None

- **Correction**

1.Revise mistake of “When B1z ROR size isn’t zero, then save to PLC, will lead to Ladder Checksum Error”.

2.Revise mistake of “B1 cannot enter C96~C199 , C220~C255 ,T220~T255 ” ◦

3.Revise mistake of “After setting 1LC & 2LC’s status of I/O Configuration, cannot save to file ” ◦